Positive – vigilant watch practices

Safety Flash Published on **31 July 2025** Generated on **1 August 2025** IMCA SF 13/25

What went right?

A member found examples of very vigilant watch practices. It was observed that for three days and nights during a very complex operation near to five fixed offshore platforms, none of the Officers of the Watch or bridge crew used any mobile devices whilst on duty on the bridge.



IMCA Safety Flashes summarise key safety matters and incidents, allowing lessons to be more easily learnt for the benefit of the entire offshore industry.

The effectiveness of the IMCA Safety Flash system depends on the industry sharing information and so avoiding repeat incidents. Incidents are classified according to IOGP's Life Saving Rules.

All information is anonymised or sanitised, as appropriate, and warnings for graphic content included where possible.

IMCA makes every effort to ensure both the accuracy and reliability of the information shared, but is not be liable for any guidance and/or recommendation and/or statement herein contained.

The information contained in this document does not fulfil or replace any individual's or Member's legal, regulatory or other duties or obligations in respect of their operations. Individuals and Members remain solely responsible for the safe, lawful and proper conduct of their operations.

Share your safety incidents with IMCA online. Sign-up to receive Safety Flashes straight to your email.